


For point contacts, the flatness and parallelness of the two surfaces is not critical, but for area contact it becomes more critical



UNLESS OTHERWISE STATED:
 1. ALL DIMENSIONS IN MILLIMETRES
 2. TOLERANCES: 0.2 mm
 3. SURFACE FINISH: GROUND
 REMOVE ALL SHARP EDGES

Designed by harveyt	Drawn by harveyt	Material Project dependent	Date 30/08/2017
 National Centre for Advanced Tribology at Southampton		Title Disc for PoD	
		Project PoD samples	Sheet 1 / 1